

## Spare parts ATEX Explosion proof electric chain hoists

	D	D/G	GCH 250/500	GCH 1000	GCH 1600/2000/2500
Stator 3Ph 230/400V 50Hz, -N, Klixon 140°	X	X	9402.0105.3	9407.0205.3	9407.0104.3
Stator 3Ph 230V 50Hz, -NF, 2 Klixon 140°	X	X	9402.0314.3	9407.0507.3	9407.0411.3
Stator 3Ph 400V 50Hz, -NF, 2 Klixon 140°	X	X	9402.0307.3	9407.0506.3	9407.0406.3
Stator 3Ph 230V 50Hz, -SF, 2 Klixon 140°	X	X	9402.0314.3	9407.0411.3	9407.0411.3
Stator 3Ph 400V 50Hz, -SF, 2 Klixon 140°	X	X	9402.0307.3	9407.0406.3	9407.0406.3
Bearing chain wheel IP 65	X	X	0038.1218	0038.1151	9038.0024
Cable gland EEx M20 x 1.5 RD	X	X	9055.3112	9055.3112	9055.3112
Cable gland EEx M25 x 1.5 RD	X	X	9055.3113	9055.3113	9055.3113
Overpressure monitoring Norgren, complete		X	9400.3062.4	9405.3079.3	9408.3056.3
Cover (overpressure monitoring at travel trolley)		X	9250.2019.4	9260.2036.4	9270.2072.4

## Spare parts ATEX Explosion proof electric travel trolley

	D	D/G	EMFE 50	EMFE 150	EMFE 300/500
Stator 3Ph 220/380/420V 50Hz, -N, Klixon 140°	X	X	9245.1102.4	9245.1102.4	9245.1102.4
Stator 3Ph 220/240V 50Hz, -NF/-SF, Klixon 140°	X	X	9245.1318.4	9245.1318.4	9245.1318.4
Stator 3Ph 380/420V 50Hz, -NF/-SF, Klixon 140°	X	X	9245.1317.4	9245.1317.4	9245.1317.4
Bearing motor cover IP 65	X	X	0038.1145	0038.1145	0038.1145
Brake complete IP 65, 151-240V 50/60Hz	X	X	9245.4020.4	9245.4020.4	9245.4020.4
Brake complete IP 65, 301-500V 50/60Hz	X	X	9245.4019.4	9245.4019.4	9245.4019.4
Cable gland EEx M16 x 1.5 RD	X	X	9055.3111	9055.3111	9055.3111
Cable gland EEx M25 x 1.5 RD	X	X	9055.3113	9055.3113	9055.3113
Overpressure monitoring Norgren EMFE 50-300, complete		X	9248.2008.3	9248.2008.3	9248.2008.3
Overpressure monitoring Norgren EMFE 500, complete		X	-	-	9281.1146.3

D = Dustproof execution, Ex II 3 D IP 65 T 130°C

D/G = Gasproof execution, Ex II 3 D IP 65 T 130°C / II 3 G EEx II nZ T3